6206 Forest City Road Orlando, Florida 32810 Ph. (407) 293-2642	HVAC INSPECTION	PLUMBING ELECTRICAL GG/REMODELS AIR GONDITIONING WATTER DAMAGE RESTORATION
Submitted to:	Phone:	Date:
HFK LLC	407-476-7935	12/3/19
Address:	E-mail:	Estimator:
5339 Alpha RD Suite 300	info@buckeyerealry.net	Marshall F
City, State:	Job Location: 561 East Horatio	TECH:
Dallas TX	Maitland FL	Marshall F
LIC # CFC 057624	LIC # CAC 1816620	LIC # ER13013660

FRANK GAY SERVICES INSPECTED 3 SPLIT SYSTEMS:

1. Main Building

EDANIK CAV CEDVICES

- a. CONDENSER# 1
 - i. Model # 4TTA3048D3000CA
 - ii. S/N # 13295MGD3F
 - iii. MANUFACTURE DATE: 2013
 - 1. Electronics components- good condition
 - 2. Compressor 9.02 AMP
 - 3. Condenser fan- 0.49 AMP
 - 4. Coils need to be clean
 - 5. Drains need to be cleared
 - 6. Filters need to be replaced
 - 7. Inside of condenser needs to be cleaned
- b. Condenser #2
 - i. Model # 4TTA3036B3000AA
 - ii. S/N # 13295JTM3F
 - iii. MANUFACTURE DATE: 2013
 - 1. Electronics components- good condition
 - 2. Compressor 8.95 AMP
 - 3. Condenser fan- 0.45 AMP
 - 4. Coils need to be clean
 - 5. Drains need to be cleared
 - 6. Filters need to be replaced
 - 7. Inside of condenser needs to be cleaned
- 2. Back Building- Recommend replacing this system
 - a. AHU
 - i. Model# H2B524B861
 - ii. S/N# L942479044
 - iii. MANUFATURE DATE: 1994
 - 1. Electronics components- Worn
 - 2. Blower motor- 5.5 amps Blower wheel dirty needs to be cleaned
 - 3. Coil need to be clean
 - 4. Drain need to be cleared
 - 5. Filters need to be replaced
 - 6. Inside coil has a refrigeration Issue: Coil is freezing up.
 - 7. R-22 system recommend replacement to new 410A system.
 - A. Condenser Unit
 - a. Model#ACS024A2A1
 - b. S/N# L941587268
 - c. MANUFACTURE DATE: 1994
 - i. Electronic Components- Worn
 - ii. Condenser fan- 1.25 high amp
 - iii. Condenser- 11.25 high amp, loud during operation
 - iv. Coils clean
 - v. Drain needs to be cleared
 - vi. Unit not on a condenser pad