


DRAW CURTAIN SUPPLIED BY CLIENT  
INSTALLED BY CONTRACTOR

SIDEWALK



DOCTORS OFF  
107 9'-0" CLG

PROCEDURE  
106 9'-0" CLG

OFFICE MANAGER  
105 9'-0" CLG

BREAK RM  
104 9'-0" CLG

CHECK OUT  
103 9'-0" CLG

CHECK IN 102  
10'-0" CLG

DOCTORS OFF  
125 9'-6" CLG

EXAM 3  
108 9'-0" CLG

EXAM 2  
109 9'-0" CLG

EXAM 1  
110 9'-0" CLG

MEN 114  
8'-0" CLG  
C.T.

EXAM 4  
111 9'-0" CLG

EXAM 5  
112 9'-0" CLG

EXAM 6  
113 9'-0" CLG

WOM 111  
8'-0" CLG  
C.T.

HALL  
119 9'-0" CLG

ARNP OFFICE  
122 9'-0" CLG

CLOSET  
121 8'-0" CLG

CLOSET  
120 8'-0" CLG

IT ROOM  
119 8'-0"

DRUGS  
118 8'-0"

BIO  
117 8'-0"

LAB/NURSES  
116 9'-0" CLG

1 HOUR RATED WALL WP1200

HOUR RATED WALL WP1200

SLOT FOR TRASH