NOTE: THE BOUNDARY AND TOPOGRAPHIC SURVEY ON LOT 4 WAS PERFORMED IN THE FIELD ON 09-01-2006. THE BOUNDARY AND TOPOGRAPHIC SURVEY ON LOT 7 WAS PERFORMED IN THE FIELD ON 07-13-2007 AS SHOWN IN THE

LAND SURVEYORS NOTES, NOTE # 11

A Boundary and Topographic Survey

Description

Lot 4 and Lot 7, Lake Business Park, according to the plat thereof as recorded in Plat Book 37, Pages 44 and 45, of the Public Records of Lake County, Florida.

Legend & Standard Abbreviations

Q.	=	Centerline	R/C	=	Set 5/8" Rebar, LB #6676
ROW	=	Right of Way	PRM	=	Permanent Reference Monument
CM	=	Concrete Monument	N/D	=	Set Nail and Disk, LB #6676
PCP	=	Permanent Control Point	ohp	=	Overhead Utility Lines
POB	=	Point of Beginning	PC	=	Point of Curvature
POC	=	Point of Commencement	PB_,pg_	=	Plat Book, Page
F.I.R.M.	=	Flood Insurance Rate Map	EP	=	Edge of Pavement
0.R.	=	Official Record Book		=	Utility Box
	=	Wood Utility or Power Pole	(F)	=	Dimension per Field Measurement
PT	=	Point of Tangency	(P)	=	Dimension per Plat
××-	=	Fence Line	(D)	=	Dimension per Description

Land Surveyor's Notes

- 1... Bearing Basis is a plat bearing of S 02°46'54" E along the centerline of LAKE PARK COURT
- 2... Subject to easements and restrictions of Record.
- 3... All of the above captioned property lies within F.I.R.M. Zone "X" according to F.I.R.M. panel No. 12069C 0358 D dated July 3, 2002.
- 4... This Survey is based on the Description provided, Plat information, Found Monumentation and other data acquired by this firm.
- 5... Foundations, Underground Structures, and Underground Improvements, if any, not located by this firm.
- 6... This is not a certificate of title, zoning or freedom of encumbrances.
- 7... Certification is limited only to the party or parties named hereon.
 8... Not valid without the signature and original raised seal of a
 Florida licensed surveyor and mapper.
- 9... The scope of this survey does not address environmental matters, jurisdictional boundaries and hazardous waste concerns should any of the foregoing exist.
- any of the foregoing exist.

 10... Fences were located ONLY where dimensioned and may not run straight: ownership of fences if any unknown
- run straight; ownership of fences, if any, unknown.
 11... Date of the field survey was 07-13-2007, drawn by R.S.Jr.
- 12... Type of Survey: Boundary Survey
- 13... This is Drawing File: LBP4,7.dwg

SCALE



<u>⊮</u> LB #6676

 CURVE TABLE

 CURVE
 RADIUS
 LENGTH
 CHORD
 BEARING
 DELTA

 C6 (P)(F)
 60.00'
 59.75'
 57.31'
 N28*13'13"W
 57*03'33"

 C7 (P)(F)
 25.00'
 23.55'
 22.69'
 S29*45'57"E
 53*58'05"

CONCRETE CURBING 0.5' WIDE (TYP)